



| DISPATCH  |  | CLASSIFICATION<br>S E C R E T | PROCESSING ACTION                           |
|---|--|-------------------------------|---|
| TO  | Director of Logistics                        |                               | MARKED FOR INDEXING                         |
| INFO.   | Chief, Far East Division                     |                               | NO INDEXING REQUIRED                        |
| FROM  | [REDACTED]                                   |                               | ONLY QUALIFIED PERSONNEL CAN JUDGE INDEXING |
| SUBJECT   | Approval to air condition West Wing Bldg 306 |                               | MICROFILM                                   |
| ACTION REQUIRED - REFERENCES  |  |                               |   |
| <p>REFERENCES: A. [REDACTED]-5536 - <i>IN 05139-RE-2/21</i><br/> B. DIRECTOR-77403 - <i>RE-2/22</i></p> <p>1. I realize there is little to be gained by debating what we here consider necessary or essential; however, perhaps we took approval for granted and failed to furnish you with sufficient factors bearing on the case.</p> <p>2. First, we have approval to enlarge the library. Re-adjustment of balance of space in west wing of Bldg 306 will follow a now normal pattern of renovation of all these lower base buildings which have interior wood structures in partitions, etc. As we reach each building, the climatic-rotted and insect-infested wooden parts are removed and replaced with masonry. As this is done, we can at no additional expense readjust spacing to suit our needs.</p> <p>3. Next, as to air conditioning, we have established a pattern which we hope to follow and, as I discussed at length with all interested personnel when I was in Headquarters, in September-October 1966, that we should go to package units wherever feasible to reduce electrical consumption and our overly large maintenance problem.</p> <p>4. A new condition since Reference A is that we may be able to recover an adequate package unit as we re-engineer the air conditioning of the Club and Mess building. If so, there would be no cost for the unit. The only direct cost would be duct work and wiring, and would recover eight window units for stock or cannibalization.</p> <p>Distribution:<br/> 2-Director of Logistics<br/> 1-C/FE Division</p> <p><i>FE/LOG will take action on this. FE/DIV now desires approve this for para 5 and</i></p> |  |                               |   |
| CROSS REFERENCE TO  | DISPATCH SYMBOL AND NUMBER                   | DATE                          |   |
|   | [REDACTED]                                   | 22 March 1967                 |   |
|   | CLASSIFICATION<br>S E C R E T                | HQS FILE NUMBER               | 25X1A                                       |
|   |  |                               | 25X1A                                       |

|                                     |                                      |   |
|-------------------------------------|--------------------------------------|---|
| <b>CONTINUATION OF<br/>DISPATCH</b> | CLASSIFICATION<br><b>S E C R E T</b> | DISPATCH SYMBOL AND NUMBER<br> |
|-------------------------------------|--------------------------------------|---|

25X1A

5. Approval is requested to centrally air condition the west wing of Bldg 306 if a no cost air conditioning unit becomes available.

6. A cable reply would be appreciated.



25X1A